


Appendix A: Site Reconnaissance Photographs (November 22, and December 2, 2013)

This page intentionally left blank.



Interior 1 - Chemical Drums inside Building 5



Interior 2 –Sodium Hypochlorite Solution inside Building 5



Exterior 1 – Engine/Generator Trailer with AST below outside of Building 5



Exterior 2 - Drums of Propylene glycol



Exterior 3 – Close up of Propylene Glycol Drum



Exterior 4 – Close-up monitoring well east of Playground



Exterior 5 - Monitoring well east of Playground



Exterior 6 – Close up additional monitoring well east of Playground



Exterior 7 - Additional monitoring well east of playground



Exterior 8 – Close up damaged monitoring well south of playground



Exterior 9 - Damaged monitoring well south of playground



Exterior 10 - Close up monitoring well Volpe Courtyard



Exterior 11 - Monitoring well Volpe Courtyard



Exterior 12 - Close up monitoring well outside Daycare Facility



Exterior 13 - Monitoring well outside Daycare Facility



Exterior 14 - Close up monitoring well near Silo Building



Exterior 15 - Monitoring well near Silo Building



Exterior 16 - H&A monitoring well (1 of 4) for 225 Binney St. study



Exterior 17 – Close up of two H&A monitoring wells (2&3 of 4) for 225 Binney St. study



Exterior 18 - Two H&A monitoring wells (2&3 of 4) for 225 Binney St. study



Exterior 19 - Close up H&A monitoring well (4 of 4) for 225 Binney St. study



Exterior 20 - H&A monitoring well (4 of 4) for 225 Binney St. study